


Bowl feeders were purchased to handle this window crank assembly. It has an internal coil spring topped with grease. Results: grease lined bowls and **unreliable** performance.

Spectrum developed a floorbin elevator, straightline vibratory orientor and track package to reliably feed the greasy assemblies.

A special mechanism was included in the track to probe for spring presence and radially position coil tangs.

Spectrum feeders and mechanical accessories will perform to meet **your** needs with reliable and cost effective simplicity.



Try Spectrum, first,...

... when you need feeders.

You'll profit sooner.

Call, write, or drop in for first effort solutions.



34447 SCHOOLCRAFT, LIVONIA, MICH. 48150 • PHONE (313) 522-2160 • FAX (313) 522-4671