

This machine delivers bolts and screws to: threadrollers; burnishers; trimmers; pointers; and other fastener making machines. It will orient and feed 1/4 to 5/8 inch diameter parts to 6 inches long.

Here, you see 3/8 inch diameter x 1-1/2 inch long hex bolts being fed at 1200 pieces per minute. That's right — 1200 pieces per minute.

## Fed up with...

... poor feeder performance?

Get the performance you need from Spectrum; *the* feeder people.

Call, write or drop in anytime.

