

# *Pick, Place & Rotate...*




Flex Plate Bolts are bulk stored, elevated, vibratorally oriented, live fed and escaped to a pick-and-place unit.

A rotary indexer, with seven position bolt tooling plate is loaded by the pick-and-place every 20 seconds.

A robot picks up the seven parts and transfers them to assembly.

Similar Fly Wheel Bolts are used in an adjacent station. Hence, the orientor tooling includes a feature to eject rogue bolts.



Call: (734) 522-2160 Fax: (734) 522-4671

E-mail: [sales@spectrumautomation.com](mailto:sales@spectrumautomation.com) or drop in!

34447 Schoolcraft Road Livonia, MI. 48150

[www.SpectrumAutomation.com](http://www.SpectrumAutomation.com)